

DIRECTV Set-top box information for the installer - Problems and Peculiarities

Published by



DTV-MD-0058a

(Rev. 1.3)

January 3, 2007

DIRECTV PROPRIETARY

**This document contains proprietary information and except with
written permission of DIRECTV such information shall not be
published and this document shall not be duplicated or distributed,
in whole or part.**



REVISION HISTORY			
Revision	Date of Issue	Author	Scope
1.0	September 1, 2005	D. K.	Initial version
1.1	October 19, 2005	J. G.	Updated formating
1.2	January 3, 2007	W. M.	Version skipped.
1.3	January 3, 2007	W. M.	Updated information regarding D10, D11 and R15



Table of Contents

<u>Section</u>	<u>Page</u>
1 Introduction.....	4
1.1 Disclaimer.....	4
1.2 Scope.....	4
1.3 Feedback.....	4
2 Known Peculiarities or Problems	5



1 Introduction

1.1 Disclaimer

DIRECTV makes no representations or warranties, express or implied, that use of the technologies described in this specification will not infringe patents, copyrights, or other intellectual property rights of third parties. Nothing in this specification should be construed as granting permission to use any of the technologies described. Anyone planning to make use of technology covered by the intellectual property rights of others should first obtain permission from the holder(s) of the rights. This specification is subject to change without notice. DIRECTV does not accept any responsibility whatsoever for any damages or liability, direct or consequential, which may result from use of this specification or any related discussions. These specifications are provided “as is” and the user of these specifications assumes any and all risks associated with the use of these specifications. DIRECTV expressly disclaims any and all representations or warranties, express or implied, regarding the specifications, including without limitation any warranty as to merchantability, fitness for a particular purpose, non-interruption of use, or non-infringement.

1.2 Scope

This document provides information on problems and peculiarities of the DIRECTV set top box data port, front panel, and remote control commands as an aid for installers, and auxiliary devices. This document is relevant to set-top box (STB) models D10-100, D10-200, D10-300, D11, R15 and H10. Other models are not supported by this document.

1.3 Feedback

Email feedback to custominstallsupport@directv.com



2 Known Peculiarities or Problems

Item #	Model	S/W Version	Description	Status
1	D10-all	--	GetCommandVersion not supported.	Final
2	D10-all	--	OSDOff command removes all on screen graphics and only video remains.	To be fixed.
3	H10	0.4.33	All commands need a carriage return to be recognized. Therefore each command string input must be followed by 0x0D (the carriage return hex code).	Final
4	H10	0.4.33	GetCommandVersion not supported	Final
5	RC23 and RC24 Remote	all	Key 0xF8 Format key is only available on the RC24 remote control and supporting products.	Final
6	D11	1040	Default baud rate is 9600.	Final
7	R15-100	1029	Support data port commands from this version up.	Final
8	R15-300	104B	Support data port commands from this version up.	Final
9	R15-500	10FA	Support data port commands from this version up.	Final